

Rail Repair



PRESSURE SENSORS, ACTUATOR & LIMITER

**** DISCOUNTS AVAILABLE FOR ACCOUNT CUSTOMERS ****

**** DISCOUNTS AVAILABLE ON BULK ORDERS ****



M002-050 (equivalent to: 45PP3-1 / 45PP3-4 / 1570-P1)

£40.00

Pressure sensor

Ford Transit 2.2 & 2.4 / Citroen Relay 2.2 & 2.4 / Fiat Ducato 2.2 & 2.4 / Mitsubishi 4D56 / Isuzu / Land Rover 2.2 & 2.4



M002-051 (equivalent to: 1497165)

£58.00

Pressure Limiter

Ford Transit 2.2 & 2.4 / Citroen Relay 2.2 & 2.4 / Fiat Ducato 2.2 & 2.4 / Mitsubishi 4D56 / Isuzu / Land Rover 2.2 & 2.4



M002-052 (equivalent to: 499000-6141 / 499000-6160)

£85.00

Pressure sensor

Isuzu



M002-053 (equivalent to: 55PP06-03 / 9658227880 / 1920GW)

£50.00

Pressure sensor

PSA 1.4,1.6 & 2.0 HDI / Citroen C2,C3,C4,Xsara, Darcia / Peugeot 107,206,207,307,308,407 Partner / Fiat 1.4, 1.6 & 2.0 / Ford 1.4,1.6 TDCI / Suzuki / Mazda 02-11



M002-054 (equivalent to: 499000-6121 / 89858-71010)

£70.00

Pressure sensor

Toyota Hilux 2AD-FTV



M002-055 (equivalent to: 55PP09-01)

£55.00

Pressure sensor

VW various models / Audi A4,A5,A6,A8,Q7



M002-056 (equivalent to: 89458-60010)

£55.00

Pressure sensor

Toyota 2AD-FHV / RAV4 / Avensis III '09, Corolla 2.5 D4D 2003, Hilux 3.0 D4D

01772 694130

www.merlindiesel.com



Rail Repair

PRESSURE SENSORS, ACTUATOR & LIMITER



M002-057 (equivalent to: 499000-6131)

£85.00

Pressure sensor

Toyota



M002-058 (equivalent to: 85PP26-03)

£55.00

Pressure sensor

VW 1.6 TDI / Variant / 4 Motion / Golf Plus / Jetta / Passat / Santana 2009>/ Polo / Derby 2010> / Audi A3, S3, Sportback 2009>, A3 Cabrio 2008>, Seat Altea 2007>, Ibiza 2009>, Leon/Leon 4 2006>, Skoda Octavia



M002-059 (equivalent to: 55PP34-01 / 96 700 767 80)

£45.00

Pressure sensor

Peugeot / Citroen / Ford / Mazda / Volvo (All 1.4 & 1.6)



M002-060 (equivalent to: 04L130764C-NEW)

£50.00

Actuator

VW Audi



M002-061 (equivalent to: 55PP04-01 / 5WS40050)

£45.00

Pressure sensor

Land Rover Discovery MK3 2.7 TDV6



M002-062 (equivalent to: 499000-6141)

£85.00

Pressure sensor

Isuzu



M002-063 (equivalent to 5WS40209 / 55PP19-01)

£45.00

Pressure sensor

Land Rover, PSA, 2.7V6 Upgrade



M002-064 (equivalent to 5WS40755 / 55PP40-01)

£45.00

Pressure sensor

Transit 2.2 Continental



M002-065 (equivalent to 55PP24-02)

£45.00

Pressure sensor

VW Audi V6 2.7/3.0

DISCOUNTS AVAILABLE ON BULK BUYS